# Oil Field Environmental Incident Summary

**Responsible Party:** Quale Trucking LLC **Well Operator:** EOG RESOURCES, INC.

Well Name: WAYZETTA 31-3230H

Field Name: PARSHALL Well File #: 25647

Date Incident:7/25/2014Time Incident:01:30Facility ID Number:County:MOUNTRAILTwp:153Rng:90Sec:32Qtr:

Location Description: spill was 1/4 mile west of 79th street Tee intersection on the south side of the

road off of Hwy 23. Production water was released into the road ditch.

Submitted By: Ross Chaffin Received By:

Contact Person: Ross Chaffin

9552 41st St NW

New Town, ND 58763

General Land Use: Other - Described Above Affected Medium: Topsoil

Distance Nearest Occupied Building:1.5 MileDistance Nearest Water Well:1.5 Mile

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike Reported to NRC: Unknown

Spilled Units Recovered Units Followup Units

Oil

Brine 4 Barrels 2 Barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: Clean Up Concluded:

**Risk Evaluation:** no immediate risk

Areal Extent:

10 foot by 30 foot

# Potential Environmental Impacts:

very little chance of impacting surface or ground water do to the location and the soil make up. There weren't any water sources around to contaminate and the soil had a lot of clay in it making absorption very slow. Clean up was immediately started when trailer began to leak.

### Action Taken or Planned:

Vac truck was on scene when the trailer began to leak, sucking up the spilled water from the ground. Dirt dike was built to prevent the spill from covering a lot of area.

Wastes Disposal Location: Clean Harbors

Agencies Involved: Mountrail County Emergency Management

# **Updates**

Date: 7/25/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

Vehicle accident due to muddy road. Trailer rolled over, and apparently a seam opened on the trailer and began leaking as transfer proceeded. Response was to build a berm in the ditch in front of the flow, and then recover the leaking brine there. County emergency manager was on scene. Strata has been retained as cleanup contractor. Followup to confirm adequate cleanup is necessary.

Date: 11/18/2014 Status: Inspection Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

11-18-14 - 12:08 on location. Location is 152-91-2 NE. Physical description of the impact location accurate, except that it is at the head of a drainage, with a culvert running under the road (flow to the NE) at the east end of the impact zone. Sparce to no vegetation restablishing in the impact area over the summer. However, there is little chance of any noticable impact with future runoff events. No further inspections needed unless vegetation stress is reported in the drainage north of the road in 153-90-32 SW.

Date: 4/18/2016 Status: Correspondence Author: Suess, Bill

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Bill Suess sent a No Further Action letter dated April 18, 2016.